PowerNet™ RC-03 Coldfire Firmware Release Notes 3/15/19

PIC v33.04

- Fixes to unlock interval timings
- Fix bug that caused valid admits during a scheduled lock event from activating the relay and unlocking the door
- Prevent REX / AUX / status update messages during a 2 factor session from having 2-factor bits applied resulting in odd audit messages in the log
- Enable Advanced HID as a factory default to match RC04 / Bridge V2

Coldfire v63.03

- Add build failures if image size exceeds the max size before the critical boot-loader erase size bug
- Mark the card DB reset as blocking during factory reset to ensure it finishes before reset